
SECTION 7 - WIRING HARNESSES



CONTROL WIRING

Reference Tables 14 and 15 starting on page 31

67217-100f

FIGURE 13 - CONTROL WIRING HARNESSES

TABLE 14 - CONTROL AND SENSOR WIRING HARNESSES

ITEM	DESCRIPTION	SYSTEM	QCC2	PART NUMBER
1	HARNESS, HIGH PRESSURE CUT OUT*	#1	ALL	575-57126-240
2		#2	ALL	575-57126-241

Service Note: High Pressure Cut-Out Harness includes High Pressure Cut-Out Switch 025-41535-000

See Figure 13 on page 31.

QUANTECH 31