

TABLE 73 - HEAT RECOVERY ASSEMBLY (CONT'D)

| ITEM | DESCRIPTION | MODEL | PART NUMBER | SAP NUMBER | FIGURE |
|-------------|------------------------|------------------------------|--------------------|-------------------|---------------|
| 130 | Rail Support, Sys 2 HR | QTC3070T, QTC3075T, QTC3085T | 092-19966-001 | 1088167 | 40 |
| 131 | Bracket Pipe Support | QTC3070T, QTC3075T, QTC3085T | 092-19966-002 | 1088168 | 40 |
| | | QTC3120T - QTC3170T | 092-07700-030 | 899779 | |
| 132 | Bracket Pipe Support | QTC3070T, QTC3075T, QTC3085T | 092-19966-003 | 1088169 | 40 |
| 133 | Bracket Pipe Support | QTC3070T, QTC3075T, QTC3085T | 092-19966-005 | 1088170 | 40 |
| 141 | Bracket Pipe Support | QTC3090T - QTC3110T | 075-75051-000 | 757570 | * |
| 142 | Bracket Pipe Support | QTC3090T - QTC3110T | 092-07700-063 | 1084723 | 41 |
| 143 | Bracket Pipe Support | QTC3090T - QTC3110T | 092-07700-070 | 1084725 | 41 |