

# HERMETIC MOTOR — MODELS MTH 67/76 AND MTH 85/95

## High—Low Voltage and Stator Sensor Wiring




FIG. 9 — HIGH AND LOW VOLTAGE AND STATOR SENSOR WIRING (See Page 22)




FIG. 10 — MOTOR TERMINALS (HIGH AND LOW VOLTAGE)